


Replacement Parts for Cutting Torches


THERMAL DYNAMICS® – PCH/M51



COMPONENTS		
Part No	Description	
1	9-5630	Shield Cup
	8-2152	Shield Cup
	8-2151	Shield Cup Long
2	8-5526	Crown Shield Cup
	8-5526-1	Crown Shield Cup
3	9-5631	Cutting Tip .043
	9-5724	Cutting Tip Gouging .078

COMPONENTS		
Part No	Description	
4	9-5633	Electrode
5	8-5525	O Ring
6	9-5635	Torch Head 70 Degree
7	9-5634	Machine Torch Head
8	8-0533	O-Ring

THERMAL DYNAMICS® – PCH/M52



COMPONENTS		
Part No	Description	
1	9-5617	Shield Cup
	9-5712	Drag Shield Cup
2	9-5694	Crown Shield Cup
	9-5694-1	Crown Shield Cup
3	9-5781	Shield Cup Long
4	9-5780	Shield Cup Metal
5	9-5708	Cutting Tip .059 100 Amp
	9-5782	Cutting Tip .052 80 Amp
	9-5707	Cutting Tip .047 70 Amp
	9-5618	Cutting Tip .043 45 Amp
	9-5702	Cutting Tip .031 35 Amp

COMPONENTS		
Part No	Description	
6	9-5710	Gouging Tip 100 Amp
	9-5709	Gouging Tip 70 Amp
7	9-5619	Electrode Air
	9-5711	Electrode Nitrogen
8	8-5525	O Ring
9	9-5642	Torch Head 70 Degree
10	9-5643	Machine Torch Head
11	8-0021	O-Ring